Oil Field Environmental Incident Summary

Responsible Party: CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: JOSEPHINE 1-8H

Field Name: SAUK Well File #: 16602

Date Incident:6/23/2016Time Incident:15:47Facility ID Number:County:WILLIAMSTwp:159Rng:95Sec:8Qtr.

Location Description:

Submitted By: Timothy Ilse Received By:

Contact Person: Ben Tarap

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Pasture Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 0.1 Barrels 0.1 Barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 7/11/2016 Clean Up Concluded: 6/24/2016

Risk Evaluation:

None

Areal Extent:

Approximately 100 ft. by 50 ft. area onsite and 50 ft. by 50 ft. area offsite.

Potential Environmental Impacts:

Vegetation and top soil

Action Taken or Planned:

Per landowner request impacted area will be monitored with no additional clean-up necessary. Impacted area onsite was bladed into the location.

Wastes Disposal Location: N/A

Agencies Involved: Called John Rumppe @ 11:20 am on 6/24/2016

Updates

Date: 6/24/2016 Status: Reviewed - Follow-up Required Author: Schiermeister, Robin

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to incident report, release impacted area off location. Follow-up is required.

Date: 6/30/2016 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 4:30, 6/30/2016.

No sign of remaining impacts at the time of inspection, with a majority of the impacted grass being mowed and removed.

No further follow-up is necessary.